

## ISIS driver for DS-860 release note

### #1. Version

ISIS driver for DS-860

Ver. 1.6.11810.25002

### #2. Supported models

- Epson DS-860

Note:

This release does not support DS-760.

Please use ver. 1.6.11501.30004 for DS-760

### #3. Support OS

Windows7 or later

Note:

This release does not support Windows Vista and older OS.

Please use ver. 1.6.11501.30004 for Windows Vista and older OS

### #4. Installation.

Since this version, both driver core and ISIS driver must be installed.

- 1) Extract "DriverCore\_860\_6430\_41.zip".
- 2) Execute "Setup.exe" in the extracted folder. Then, follow the message.
- 3) Extract "ds7\_860\_ISIS\_1\_6\_11810\_25002.zip".
- 4) Execute "Setup\_ISIS\_DS860.msi". Then, follow the message.

#5. Epson OCR Component installation required to use "Auto Rotation" feature on UI.

Epson OCR Component must be installed to use "Auto Rotation" feature.

### #6. Uninstallation

Go to Start menu - "Control Panel" - "Uninstall and change program" .

Select "ISIS Driver - EPSON DS-7\_860" and press "Uninstall" button on control panel.